Oil Field Environmental Incident Summary

Responsible Party: High Ball Transport

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: CHARGING EAGLE 14-14-10-2H

Field Name: TWIN BUTTES Well File #: 25288

Date Incident:12/12/2015Time Incident:04:00Facility ID Number:County:DUNNTwp:147Rng:92Sec:14Qtr:

Location Description:

Submitted By: Allison Christensen Received By:

Contact Person: Allison Christensen

315 Main St 556

New Town, ND 58763

General Land Use: Badlands Terrain Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well: 1 Mile

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine

Other 5 Gallons 2 Gallons 5 gallons

Description of Other Released Contaminant:

Motor oil

Inspected: Written Report Received: 3/4/2016 Clean Up Concluded: 2/18/2016

Page 1 of 2

Risk Evaluation:To be determined

Areal Extent:

5x5 area off the lease road on Charging Eagle 14-14

Potential Environmental Impacts:

To be determined.

Action Taken or Planned:

Driver was taken to hospital for precautionary measures and released. Truck was towed from the ditch. Motor oil was vac'd up from snow into produced water truck and hauled off. Assessment will take place to determine if soil will need to be removed.

Wastes Disposal Location: an approved facility

Agencies Involved: BIA, TAT, MHA, NDIC, NDDOH

Updates

Date: 12/14/2015 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release impacted areas off location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.